



Optional Freescale Accelerometer

rev2: NC pin6 of IC6 - 3.3VDD out  
led color changes  
remove 1M resistor on crystal

rev3: Add optional Freescale accel  
rev4: Separate sensor VCC; remove ADXL345; MS5611 pressure;  
each sensor interrupt pin routed; bypass cap on USB

FreeFlight Clone / AfroFlight 32

Creative Commons CC BY-NC-SA 3.0

SIZE	FSCM NO.	DWG NO.	REV 2
SCALE		Sheet 1	